



LUCAS **C.A.V.**

CE 826/70

EQUIPMENT & SPARE PARTS

ENFIELD MOTOR CYCLES

750cc Interceptor Series II (12 volt)

1970 equipment and service details for the above model are listed below:-

ALTERNATOR		CONTACT BREAKER
Model	RM21	Part No
Serviced by:-		*47644D
Stator	@47205A	(54419097 &
Rotor	@54213901	(54420472)
		Model
		6CA
AMMETER		Contact Breaker
Part No	+36403A	54419097
Model	2AR	Contact Set
		54419827
		Adjustment Pin
Nut, terminal	166043	54419220
Washer, terminal	185040	Auto Advance Unit
		54420472
		Springs, auto advance (set of 2)
		54413020
		DIODE, ZENER
BATTERY		Part No
Part No	54027029	@49345
Model	FUZ5A	Model
		ZD715
		HORN
BULBHOLDER		Part No
(speeds and Rev)		*@70197D
Part No	554710	(70183)
Bulb	643	Model
		6H
		HORN PUSH AND DIPPER SWITCH
CABLE HARNESS		Part No
Part No	54954557	31563D
		Model
(Later fitment- after frame		Screw, terminal
No.2000)		120610
Part No	54956914	LAMPS
		HEAD
CAPACITOR		(Home and Export)
Part No	54170009	Part No
Model	2MC	*59872A
Spring	54483156	(59969 and
		Bulbs 446 & 989)
		Model
		SS700P
COIL, IGNITION		Rim or door
Part No	*@45221A	553248
Model	(45223)	Wire, fixing
	17M12	504665
		Screw, fixing rim
		144921
		Plate, fixing rim
		534296
		Ammeter
		36403
CONDENSER		Warning Light body assembly
Part No	@425377	38189
Model	3CA	Sealing washer, warning light
		54140331

cont'd

Joseph Lucas (Sales and Service) Ltd., Great Hampton Street, Birmingham 18

COPYRIGHT.—All rights reserved. No part of this publication may be reproduced without permission

Headlamp Part No 59872A cont'd

REFLEX REFLECTOR
(Red)

Bulb, warning light 281
 Bulbholder, warning light 54945043
 Switch, lighting 35710
 Light unit 516798
 Bulbholder, main 554602
 Sleeve, terminal 555910
 Bulbholder, pilot 54573590
 Interior, pilot 553780
 Ring, seating pilot bulbholder 554354
 Bulb, main 446
 Bulb, pilot 989
 Connector, double 850641
 Screw, fixing lamp 112201
 Washer, lamp fixing screw 137498

Part No @57110A
 Model RER25
 (Amber)
 Part No @57162B
 Model RER25

SWITCHES

IGNITION

(Export France)

Part No *59874A
 (59970 and
 Bulbs 410 & 989)
 Model SS700P
 Light Unit 54522680
 Adaptor 553738
 Bulb 410
 Connector, single 900288
 Other details as 59872A

Part No 31899B
 Model S45
 Nut, fixing 54130041

LIGHTING

STOP LAMP

(Export Europe)

Part No *59873A
 (59970 and
 Bulbs 411 & 989)
 Model SS700P
 Light Unit 54522680
 Adaptor 553738
 Bulb 411
 Connector, single 900288
 Other details as 59872A

Part No +@31788D
 Model 57SA
 Part No 31688B
 Model 6SA
 Cover, terminal, rubber 360363
 Sleeve, terminal 188818

WARNING LIGHT
(Main beam)

Part No +@38189A
 Model WL15

+ Part of headlamp
 @ Service complete unit only

STOP TAIL NUMBER PLATE
ILLUMINATION & REFLEX

Part No 53973E
 Model 679
 Lens 54577109
 Screw, fixing lens 144921
 Bulbholder, assembly 54578213
 Interior, bulbholder 573828
 Bulb 380
 Base assembly 54578212
 Gasket, seating lamp 54571677
 Screw, fixing lamp 110714
 Washer, fixing screw 188330

* When ordering quote part number shown in brackets

RECTIFIER

Part No @49072B
 2DS506